Same boat but different recommendation for a propeller - why?

- Different type of sailor and needs might be different.
- The engine of the boats might be a little different which can result in very different recommendations you can not just look at the model and horsepower.
- The boats might be sold with different options that might influence the choise of propeller.
- The gear reduction ratio might be different (look at our explaition)
- The engine speed might be different

Here is an example:

Brand	Engine	Revolution		Seems like the same engine by name but the revolution is different and therefore the recommendation for a
Yanmar	3YM30	29/3600		
Yanmar	зүмзоаЕ	29/3200	propeller will be different as well	

Here is another example:



